## Annexure D

## **BUILDING SAFETY CERTIFICATE**

It is certified that the existing building LAKSHYA INTERNATIONAL SCHOOL (name of the building or premises) at GURWALIA MANUAPUL BETTLAH WEST CHAMPAR		Dated: .22-4-24
building or premises) at GURWALIA MANUAPUL BETTLAH WEST CHAMPAR		
	LIA MANUAPUL BE	ITLAH WEST CHAMPARA
(address) is having block(s)/Floor(s) as per details below:	ing block(s)/Floor(s) as per detai	s below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	GROWND + 2 FLOOR	GROUND + 2 FLOOR				

The building is owned/occupied by LAKSHYA TNTERNATIONAL SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of BUILDING CONSTIDER (Name of Department/ Govt.) on 22 04, 2024 (date of inspection) in the presence of KAUSHAL KISHUR STRKHANDT, WARD-09 BAGAHI, EDST CHAMPARAH (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 22-14-2024 for a period of 21.4-2025 years in accordance with rule and subject to compliance of the specific conditions as appended.

with rule and	ule and subject to compliance of the specific conditions				
1.					
2.					
3.					
4.					
Issued on	by				

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal:

Name: Rameon Pandot

Designation :

Name & Address of Department/ Office