

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. 1162

Dated: 14-08-2025

It is certified that the existing building LAKSHYA INTERNATIONAL SCHOOL (name of the building or premises) at GURWALIYA, MANUAPUL, BETTIAH, WEST CHAMPARAN (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground + 2 Floor	Ground + 2 Floor	—	—	—	—

The building is owned/occupied by LAKSHYA INTERNATIONAL SCHOOL (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of BUILDING CONST. DEPT. (Name of Department/ Govt.) on 14-08-2025 (date of inspection) in the presence of Kaushal Kishor Sexkhadi, Ward No. 9, Bagahi, East Champaran (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 14-08-25 for a period of 13-08-2025 years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on ..... at ..... by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 14.8.2025

Name : कार्यपालक अभियंता

Designation : भवन प्रबंधन, बेतिया

Name & Address of Department/Office : \_\_\_\_\_